

Ready to Weld? Protect yourself:



1) **Welder's helmet with eye shield** - protects eyes against UV rays and face from dust and welding particles

2) **Respirator with HEPA or N100 designation** - protects you from inhaling metal fumes

3) **Leather Jacket** - resists burning, and keeps dust and sparks off your street clothes

4) **Leather gloves** - protect skin from sparks and burns

Use ventilation for big welding jobs

After welding, wash hands thoroughly with soap and lots of water!