

So you need to WELD??

Make sure you wear:

- **Welding mask with eye shield**
- **HEPA or N100 respirator**
- **Leather gloves**
- **Fire retardant jacket**
- **High top leather shoes**